


V502




Step 1:

Mark the installation height on the wall, mark the position of the mounting holes, align the bracket for drilling, insert expansion tubes and screws, and secure the bracket.

Step 3:

Route the cables through the hole in the wall, then clip the unit into the slot on the bracket.

V501/V501F




Step 1:

Mark the installation height on the wall, mark the position of the mounting holes, align the bracket for drilling, insert expansion tubes and screws, and secure the bracket.

Step 3:

Route the cables through the hole in the wall, then clip the unit into the slot on the bracket.

V801



Step 1:

Mark the installation height on the wall, mark the position of the mounting holes, align the bracket for drilling, insert expansion tubes and screws, and secure the bracket.

Step 3:

Route the cables through the hole in the wall, then clip the unit into the slot on the bracket.